



ULUSLARARASI TEMSİL IFALPA BELGESİ

Belge: IFALPA Daily News – 16 August 2013

Tarih: 19.08.2013

Kaynak: IFALPA haberleri · talpa.org

Dear Colleagues,

The [IFALPA Daily News](#) is now available online.

Here are today's top headlines. To read more, click on the title:

[Heathrow Airport on high alert over Qaeda terror threat: report](#)

UK's busiest airport Heathrow has been put on high terror alert after "credible" intelligence emerged that al-Qaeda is plotting attacks, including strike by women suicide bombers with explosives concealed in breast implants, a media report said on Friday.

[Aer Arann strike suspended as pilots vote on new deal](#)

The planned strike by Aer Arann pilots, due to start next Tuesday, has been suspended to allow a negotiated agreement on pay to be put to ballot.

[Temporary Nairobi Airport terminal in eight weeks](#)

Kenya expects a temporary passenger terminal to be ready at Nairobi airport in eight weeks after fire gutted the international arrivals building and will accelerate work on a new terminal already under construction, officials said on Thursday.

[Flights to and from TIA diverted as cracks on runway resurface](#)

All domestic and international flights to and from the Tribhuvan International Airport (TIA) were diverted for nearly an hour Friday afternoon after the runway developed cracks.

[Canada broadens inspections of aircraft emergency beacons](#)

Canada on Thursday ordered airlines to inspect emergency beacons on a broad list of aircraft for possible wiring problems that could lead to a fire.

[Faulty 787 fire extinguisher traced to supplier – Report](#)

Boeing has traced the incorrectly assembled engine fire extinguishers on 787 Dreamliners to the manufacturing of bottles at a supplier's facility while saying there were no risks to flight safety, the Wall Street Journal reported.

Latest IFALPA Publications

[14POS07 – Flight deck design](#)

ICAO Annex 8 states that "the design of the flight crew compartment shall be such as to minimize the possibility of incorrect or restricted operation of the controls by the crew, due to fatigue, confusion or interference.